



AL DHAEN 36 SF WAVEBREAKER 2009



AL DHAEN 36 SF WAVEBREAKER 2009



www.royalyachting.ae

YACHT FOR SALE | AL DHAEN 36 SF 2009

BUILDER:	AL DHAEN
BUILT:	2000
LENGTH OVERALL:	11.20 METERS
BEAM:	2.87 METERS
DRAFT:	0.60 METERS
STATEROOMS:	1 CABIN
GUESTS:	2 BERTHS
FLAG:	UAE
HULL MATERIAL:	GRP

PRICE NOW: 190,000 AED

~~PRICE WAS: 230,000 AED~~

FOR MORE INFORMATION CONTACT ROYAL YACHTING



+971 (0) 4 399 6399



+971 (0) 50 467 4113 / Sales Manager



www.royalyachting.ae



**BOAT DETAILS**

Type of Boat :	Central Console
Boat Builder :	Al Dhaen
Model :	36 SF
Year :	2000
Hull Material :	GRP
Length Overall :	11.2 Meters
Beam :	2.87 Meters
Draft :	0.6 Meters
Displacement :	4.41 Ton
Fuel Capacity :	950 Liters
Fresh Water Capacity :	250 Liters
Trailer :	Yes
Location :	Dubai

MECHANICAL DETAILS

Engine :	Suzuki
Engine Power :	2 x 300 HP
Engine Hours :	340 Hours
Fuel Type :	Petrol
Propulsion :	Outboard
Maximum Speed :	44 knots
Cruising Speed :	30 knots
Aircon Power :	No

ELECTRONICS

Compass :	Yes
Chartplotter :	Yes
GPS :	Yes
Radar :	No
VHF :	Yes
Sound System :	Yes
TV/DVD :	No

ACCESSORIES

Helipad :	No
Bimini Top :	Yes
Life Raft :	No
Boat Covers :	No
Windlass :	Yes
Platform :	Yes
Swimming Ladder :	Yes
Teak Flooring :	No
Sundeck :	Yes

EQUIPMENTS

BBQ Grill :	No
Water Maker :	Yes
Outside Shower :	No
Water Heater :	Yes
Dish Washer :	No
Washing Machine :	No
Stove(s) :	No
Oven :	No
Microwave :	No
Fridge :	No
Icebox :	No
Under Water Lights :	No

LAYOUT

Main Saloon :	No
Saloon Convertible :	No
Number of Cabins :	1
Number of berths :	2
Number of Heads :	1

COMMENTS : The yacht is in satisfactory condition. The yacht have a live bait well tank. Trailer is included.

The year of the hull is 2000.
The year of the engine is 2009.

DISCLAIMER : In this transaction we are acting as Brokers only. Whilst every care has been taken in their preparation, the correctness of these particulars is not guaranteed. The particulars are intended as a guide only and they do not constitute a term of any contract. A prospective buyer is strongly advised to check the particulars and where appropriate to have the vessel fully surveyed and inspected.































